BSP for Microsoft* Windows* 7 (WIN7, WES7 & POSReady 7) 32-bit & 64-bit for Intel® Pentium® Processor N3700 and Intel® Celeron® Processor N3150, N3050 and N3000 Product Family

Release Notes

September 2015

Intel Confidential

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting: http://www.intel.com/design/literature.htm

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Learn more at http://www.intel.com/ or from the OEM or retailer.

No computer system can be absolutely secure.

Intel, Pentium, Celeron and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2015, Intel Corporation. All rights reserved.

Contents

Figures

No table of figures entries found.

Tables

No table of figures entries found.

Revision History

Date	Revision	Description
September 2015	1.1	Section 2.3 Updated Best Known Configurations information. Section 2.4 Added eMMC and SD2 driver information. Updated graphics driver naming convention.
July 2015	1.0	Initial release.

§

1.0   Introduction

1.1   Scope of Document

This document consists of Release Notes about the Intel developed GPIO*, I2C*, HS-UART driver for Windows* 7, Windows Embedded Standard 7 and Windows Embedded POSReady 7. This document also includes information about Window 7 Inbox drivers that have been validated on the Intel® Pentium® Processor N3700 and Intel® Celeron® Processor N3150, N3050 and N3000 Product Family.

In this Release Notes, driver interfaces, limitations, errata, closed issues, known issues, platform and driver software best known methods are covered.

This document is intended for OEMs and ODMs that are enabling Win7 and WES7 drivers with the Intel® Pentium® Processor N3700 and Intel® Celeron® Processor N3150, N3050 and N3000 Product Family.

1.2   System Requirements

The following Operating Systems are supported:

- Windows 7 Operating System (32-bit and 64-bit versions)
- Windows Embedded Standard 7 Operating System (32-bit and 64-bit versions)
- Windows Embedded POSReady 7 Operating System (32-bit and 64-bit versions)

1.3   Acronyms and Terminology

Term	Description
API	Application Programming Interface
ATAPI	ATA Packet Interface
BSP	Board Support Package
CRB	Customer Reference Board
DMA	Direct Memory Access
eMMC	Embedded Multimedia Card
GPIO	General Purpose Input/Output
HSUART	High Speed Universal Asynchronous Receiver/Transmitter
I2C	Inter-Integrated Circuit
IO	Input Output

Term	Description
IOCTL	Input Output Control
KITL	Kernel Independent Transport Layer
LAN	Local Area Network
MSDN	Microsoft* Developer Network
OS	Operating System
PCI	Peripheral Component Interconnect
SATA	Serial ATA
USB	Universal Serial Bus

§

2.0   Release Summary

2.1   Release Details

Driver Version: 1.2.3.0616

Released: September 2015

2.2   Release Contents

The contents of this release include:

- Intel® Processor Win7 IO Drivers 32Bit and 64Bit Driver Installer

- Both "Intel Processor Win7 IO Drivers 32Bit.msi" and "Intel Processor Win7 IO Drivers 64Bit.msi" installers will install the following drivers on your system:
  - Intel® Celeron®/Pentium® Processor UART Host Controller
  - Intel® Celeron®/Pentium® Processor I2C Controller
  - Intel® Celeron®/Pentium® Processor GPIO Controller
  - Intel® Celeron®/Pentium® Processor Low Power Subsystem DMA Device

- Intel® Processor Win7 IO Drivers – Software Developer Guide
  - Headers Files for GPIO and I2C
  - Software Developers Manual for Windows 7 IO Drivers

- Intel® Processor Win7 IO Drivers Release Notes & User's Guide

- Intel® Software License Agreement

2.3   Best Known Configurations

Hardware Configuration		
Category	**Description**	**Rev/Type/ Source**
CRB	Cherry Hill	Rev E Fab 205
SOC	Intel® Pentium® Processor N3700 and Intel® Celeron® Processor N3150, N3050 and N3000 Product Family	C0: QJ4S
Display	HDMI	
Memory	Cherry Hill: 4 GB DDR3 (2x2GB)	
Firmware Configuration		
CRB BIOS	BSW_SPI_Quad_R12_Config1_Production_BRASWEL_X 64_R_X080_00_ME-2.0.0.2073 (vBIOS 1008)	Refer to BIOS release
KSC	N/A	N/A
Driver/OS Configuration		
Operating System	Windows 7 SP1 Windows Embedded Standard 7 SP1 Windows Embedded POSReady 7 SP1	MSDN
Graphics Driver	38.15.0.1081/15.38.5.64.4277	Intel graphics driver
GPIO Driver	1.2.2.1008	Intel
I2C Driver	1.2.2.1008	Intel
SPI Driver	N/A	N/A
HS–UART Driver	1.2.3.1010	Intel
SD and eMMC Driver	1.2.3.1010	Intel
DMA	1.2.3.1010	Intel
Chipset INF	10.1.1.7	Intel
USB 3.0 Driver	4.0.0.36 (32bit and 64bit)	Intel

2.4 The Ready Feature

Area	Feature	Source	Ready[1]
SIO	General SIO Feature	Win7 Inbox driver	Yes
USB	General USB 2.0 Feature	Win7 Inbox driver	N/A
	General USB 3.0 Feature	Intel USB 3.0	Yes
	USB3.0 Boot	Win7 Inbox driver	Yes
SATA	General SATA Feature	Win7 Inbox driver	Yes
	General SATA2 Feature		N/A
	General SATA3 Feature		Yes
PCIe*	General PCIe Feature	Win7 Inbox driver	Yes
Intel(R) Graphics Driver	General graphics Feature	Intel	Yes
High Definition Audio	General HD Audio Feature	Win7 Inbox driver	Yes
	HDMI Audio	Integrated in Intel graphics driver	Yes
Power Management	Power Mgmt S0 and S5	N/A	Yes
	Power Mgmt Sleep S3	Intel	Yes
	Power Mgmt Hibernate S4	Intel	Yes
GPIO Driver[1]	Direction Setting	Intel	Yes
	Multiplexing Setting		Yes
	Level Value Setting		Yes
	Pin Setting Query		Yes
I2C Driver[1]	Standard Mode (100Kbps)	Intel	Yes
	Fast Mode (400Kbps)		Yes
HS-UART Driver[1]	Baud rate support up to 4000000	Intel	Yes
	Data size 5, 6, 7, 8-bit		Yes
	Odd, Even, None Parity		Yes
	1, 1.5, and 2 Stop Bits		Yes
	Hardware & No Flow Control & Software Flow Control		Yes
DMA Feature[1] (I2C, SPI, HS-UART)	DMA support for I2C and HS-UART	Intel	Yes
eMMC Driver	Version 4.5 Storage	Intel	Yes
SD2 Driver	SD and SDHC Cards	Intel	Yes
	Class 2,4,6 and 10		Yes
	1-bit and 4-bit Bus Mode		Yes

	FAT32, NTFS, exFAT File System		Yes
	Advanced Direct Memory Access (ADMA) transfer mode		Yes

Note: Refer to the next section for the limitations of the GPIO/I2C/HS-UART/DMA feature.

§

3.0 Release Notes

3.1 GPIO Driver

The GPIO Driver interface is exposed by a series of IOCTLs. A separated C header file provides the definition of the IOCTLs and a separated programming guide provides how to program with the IOCTLs.

Driver Binary Package:

- iaiogpio.inf
- iaiogpio.sys
- iaiogpio.cat

Driver Interface Header:

- GPIOPublic.h

Enabled Features:

- Support GPIO multiplexing setting.
- Support GPIO setting query, query multiplexing information of GPIO pin.
- Support GPIO direction setting, configure selected GPIO pin as input or output pin.
- Support GPIO read pin, read pin's level value when GPIO pin is configured as input pin.
- Support GPIO write pin, configure pin level to high or low when it is configured as output pin.

Limitations:

- No known limitation

3.2 I2C Driver

The I2C Driver interface is exposed by a series of IOCTLs. A separated C header file provides the definition of the IOCTLs and a separated programming guide provides how to program with the IOCTLs.

There are a total of seven I2C controllers on the Intel® Atom™ E3000 Processor, Intel® Celeron® Processor N2XXX and Intel® Celeron® Processor J1XXX which share the same DMA engine. Hence, transferring a relatively large data size (relative to normal I2C bus usage) will cause one I2C controller to occupy DMA engine for a long duration.

The application can use multiple single transfers or IOCTL_I2C_EXECUTE_SEQUENCE interface to transfer big data.

By default, I2C driver uses DMA to copy data between peripheral and system memory, but can set Windows registry to disable DMA feature and copy data by PIO mode. Refer to the BKM section regarding how set the registry.

Driver Binary Package:

- iaioi2c.inf

- iaioi2c.sys

- iaioi2c.cat

Driver Interface Header:

- I2CPublic.h

Enabled Features:

- Support 7-bit address Mode

- Support Standard Mode (100Kbps)

- Support Fast Mode (400Kbps)

- Support polling of IO data transfer

Limitations:

- The maximum single transfer size is limited to 64Kbytes. Multiple transfer is required for data size of more than 64KB.

3.3   HS-UART Driver

HS-UART Driver interface is exposed by standard Windows Serial Communication interface. Refer to Serial Communications in Win32 in MSDN to understand the details. http://msdn.microsoft.com/en-us/library/ms810467.aspx

Following APIs of serial communication in Win32 are supported in MR1 driver release:

- SetCommMask

- WaitCommEvent

- GetCommMask

Remark: These serial series masks: "SERIAL_EV_PERR, SERIAL_EV_RX80FULL, SERIAL_EV_EVENT1, SERIAL_EV_EVENT2" used in the above three functions are not supported. Others are supported.

Intel has no plan to support the following APIs of serial communication in Win32:

- SetupComm

- [SetCommBreak](#)

- [ClearCommBreak](#)

- [EscapeCommFunction](#) (no support for parameter set to SETBREAK and CLRBREAK)

Driver Binary Package:

- iaiouart.inf

- iaiouart.sys

- iaiouart.cat

Driver Interface Header: See MSDN as above link.

Enabled Features:

- Support baud rates: as specified in the "N-series Intel® Pentium® Processors and Intel® Celeron® Processors External Design Specification (EDS)" (document# 547869) Section 16.3.2.3 Baud Rate Generator.

- Support data size of 5,6,7, and 8-bit

- Support none, odd and even parity

- Support 1, 1.5, and 2 stop bits

- Support "Hardware" and "No" flow control and software flow control

- Supports Serial Device Control Requests (IOCTLs) defined by MSFT for serial controllers in Windows. See Limitations below for the IOCTLs that will be enabled in Gold release.

Limitations:

- HS-UART driver doesn't support DMA transfer with software flow control. When application uses the software flow control, the HS-UART will use PIO mode to copy data between peripheral and system memory.

- Software flow control only supports a maximum baud rate up to 115200. Recommended to use hardware flow control for data transfer for high baud rate.

- When 1.5 stop bits is used, the data size can only be supported up to 5 bits.

- IOCTLs are not supported in driver:

IOCTL_SERIAL_XOFF_COUNTER

IOCTL_SERIAL_LSRMST_INSERT

IOCTL_SERIAL_SET_BREAK_ON

IOCTL_SERIAL_SET_BREAK_OFF

BSP for Windows 7 IO for Intel® Pentium®/Celeron® Processor N3000 Family
September 2015   Release Notes
Document Number: 557859-1.1   **Intel Confidential**   13

3.4　LPSS DMA Driver

LPSS DMA Driver is not exposed publicly and only I2C, HS-UART drivers are able to access the DMA driver interface.

3.5　Errata, Closed Issues, Known Issues

3.5.1　Errata

Issue #	Description	Impact	Recommendation
4634937	HS-UART COM number increases every time after uninstall/reinstall of UART driver	For those applications using COM ports of HSUART, user need to enable changing input parameter of COM number	Change the HS-UART COM ports in the application whenever the UART driver is reinstalled.
4635034	System unable to load into Windows after wake up from hibernate by hitting USBkeyboard and mouse when XHCI mode in BIOS is set to 'Auto' or 'Smart Auto'	User failed to resume the system back from hibernate when XHCI mode is set to "Auto" or smart Auto	Change XHCI mode to "Enable".

3.5.2　Closed Issues

Issue #	Description	Resolution
5221317	[CHV][WIN7] USB3.0 pendrive unable to be detected intermittently after SUT 1st reboot or shut down	Recommended to use C0 Stepping.
5221319	[BSW] Low volume from the back panel green audio jack during audio playback	Change of series capacitor for audio line out C1B92 and C2B10. Refer to latest Cherry Hill Customer Reference Board Fab E schematic.
5221356	HSUART/UART don't support more than 1Mbps due to transceiver limitation.	Fixed with changes of UART transceiver part U5R2 and U5R3. Refer to latest Cherry Hill Customer Reference Board FAB E schematic.
5221393	[CHH][WIN7] Several devices yellow bang in Device Manager	Fixed in BIOS version V73.
5221401	USB keyboard and mouse not functioning in Windows Advance Boot Option page	Fixed in BIOS. Recommended to use BIOS version 73 or higher.

3.5.3　Known Issues

Issue #	Description	Impact	Recommendation
4994734	Super Speed USB 3.0 Pendrive Performance Drop in WES 7	WEC7 USB3.0 Super Speed thumb drive , for example Lexar* JumpDrive* P10 USB 3.0 Flash Drive 32GB (up to	Use the standard USB3.0 Pen Drive, for example Corsair Voyager (up to 80MB/s read, 40MB/s

Issue #	Description	Impact	Recommendation
		265MB/s read, 245MB/s write).	write).
5221392	[CHH][WIN7] USB3.0 Read/Write not up to expectation.	Very fast USB3.0 device will notice drop in performance.	Still can be used and within USB3.0 range.
5221464	[CHH][WES7]UART data mismatch when running the test with None and Software flow control	Customer cannot use HS-UART at certain baud rate reliably.	Use hardware flow control

§