

BTW 3.0.1.901



Release Notes

BTW 3.0.1.901

April 13, 2004

Confidential and Proprietary Information



Wireless Internet and Data Communication

© WIDCOMM Inc., 1999 - 2004, All rights reserved.

Printed in United States of America.

9645 Scranton Road, Suite 205

San Diego, CA 92121

Phone: (858) 453-8400

Fax: (858) 453-5735

Email: support@widcomm.com

LICENSED SOFTWARE

BTW 3.0.1.901

© Copyright 1999 - 2004, WIDCOMM, Inc. ("WIDCOMM"). All rights reserved.

WARNING:

This software and accompanying documentation are protected by copyright law and international treaties. Unauthorized reproduction or distribution of this software, or any portion of it, may result in severe civil and criminal penalties, and will be prosecuted to the maximum extent possible under the law.

Use of this software is governed by the terms of the end user license agreement that accompanies or is included with such software. Unless otherwise noted in the end user license agreement, or herein, no part of the documentation accompanying this software, whether provided in printed or electronic form may be reproduced in any form, or stored in a database or retrieval system, or transmitted in any form or by any means, or used to make any derivative work (such as translation, transformation, or adaptation) without the express, prior written consent of WIDCOMM.

Trademark(s) TM and Registered Trademark(s) ®

WIDCOMM and the WIDCOMM logo are trademarks of WIDCOMM, Inc.

Bluetooth is a trademark owned by the Bluetooth SIG, Inc., and used by WIDCOMM under license.

Microsoft and Windows are registered trademarks of Microsoft Corporation.

Other brand and product names may be registered trademarks or trademarks of their respective holders.

BTW 3.0.1.901

Installation

SOFT00019239

Enable FAX, BIP and audio in custom.ini for HP releases

Release Note:

Enabled audio and fax service/apps for HP.

Installation

Stack Server

SOFT00019557

Sending disconnect when should be sending a thumbnail.

Release Note:

Now it sends thumbnail on Partial Content response code.

Stack Server

General

SOFT00019547

If BIP server doesn't contain ATTR_ID_SERVICE_NAME BIP will return
WBT_ERR_SERVICE_NOT_FOUND

Release Note:

If BIP server doesn't contain ATTR_ID_SERVICE_NAME client side will work with first found BIP service

General

SOFT00019553

BTW 3.0.1.901 Merge

Release Note:

N/A

General

BTW 3.0.1.901

Major Additions from BTW 1.4

1. BIP option controlled by license.
2. HFP profile implemented.
3. Bluetooth 1.2 support.
4. AFH implemented.
5. Extended HID handling.

Known Limitations

1. User must be logged on as administrator to install BTW. If non-administrative user is logged on and starts install, and then inputs administrator password, BTW will not install correctly.
2. If the system is configured to share contacts between Outlook Express and Microsoft Outlook, Outlook Express will not be shown as one of the options for PIM Item Transfer for business cards.
3. If the client is set for NAP service, the Bluetooth Network adapter will not show that it is disconnected. Before using another Network access point, either reboot or manually renew the ip address.
4. Install Shield Developer 8.0 Service Pack 2 is required to build the BTW Release.
5. In order to see traces in SpyLite, you will need to do the following:

Create this registry entry:

```
DWORD HKCU\Software\WIDCOMM\BTConfig\Debug\LogIPAddr = 0x7f000001  
Reboot.
```

BTW 3.0.1.901

Installation Command Line Options

To install BTW from command line prompt or from a batch file, use the following command line options:

Setup.exe [/qn | /qb | /qr] [/L<LangId>] [/ru] [/ri]

/qn - Silent install without any UI and user interaction

/qb - Silent install with basic UI with progress dialog without any user interaction

/qr - Silent install with full UI without any user interaction

/L -Installation language

<LangId> can be one of the following

1033: English

1046: Portuguese

1028: Chinese Tradition

2052: Chinese Simplified

1030: Danish

1043: Dutch

1035: Finnish

1036: French

1031: German

1040: Italian

1041: Japanese

1042: Korean

1044: Norwegian

1034: Spanish

1053: Swedish

/ru - Suppress reboot at the end of uninstall. (Relevant for Windows 98 and ME during upgrade)

/ri - Suppress reboot at the end of install (Relevant for Windows 98 and ME and if reboot is required on Windows 2000)

For example, to install silently without any UI in German language, use the following command line

setup.exe /qn /L1031